

JABIRU AIRCRAFT PTY LTD

P.O. Box 5792
Bundaberg West
Queensland, Australia.

Phone:
Fax:
Email:

+61 7 4155 1778
+61 7 4155 2669
info@jabiru.net.au

SERVICE BULLETIN: JSB 018-3

Issue: 3

Date: 15th October 2014

Subject: Jabiru Engine Tuning

Issue	Reason for Issue	Revision Status
1	Original Issue	CANCELLED
2	New Information Added	CANCELLED
3	Service Bulletin JSB 018-2 cancelled entirely, refer to engine manuals	

1 Applicability

All Jabiru Engines.

Note: For aircraft in Light Sport Aircraft categories this Bulletin is equivalent to a Manufacturer's Safety Directions.

2 Service Bulletin Cancellation

This issue has been released to cancel the Service Bulletin JSB018-2 in its entirety. All directions, instructions and procedures provide in this document are to be disregarded.

All information regarding the Tuning of Jabiru engines should be sourced from the Engine Manuals, specifically:

- The latest issue of JEM0001 - Engine Overhaul Manual
- The latest issue of JEM0002 – Engine Maintenance Manual